## EXECUTIVE SUMMARY OCCUPATIONAL SAFETY AND HEALTH APPEALS BOARD

## Summary of Duke Pacific, Inc - Decision After Reconsideration

Failure to follow its written procedure to tack weld a roof girder prior to removing temporary support established a violation of 1509(a) for failing to assess new hazard. Serious, accident related violation of section 1716.1(c)(1)(A) shown when employee on steel girder fell over 19 feet because he was working at that height without fall protection when girder unexpectedly gave way.

Duke Pacific Inc. 06-5175 through 5177 March 14, 2012 **1509(a), 1716.1(c)(1)(A)**